

Public Notice No. 17-001

Public Notice Under Rule 51.332

CenturyLink's Internet address:

http://www.centurylink.com/wholesale/networkdisclosures.html

Copper Retirements in Florida, Ohio, Virginia, and Wisconsin.

First Implementation Date: August 30, 2017 Original Date Posted: February 3, 2017

Summary:

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

Description of any changes in rates, terms or conditions that will accompany the planned change(s):

As a general matter, the retirement of these copper facilities will not result in changes to rates, terms and conditions in c ases where the affected service is converted to a like-for-like service that is available on the replacement fiber or copper facilities. Interconnecting entities, however, should review the applicable tariff or agreement for certain terms that may apply specifically in cases where the service is provisioned on fiber. In cases where interconnecting entities elect to replace the affected service with an alternative service that CenturyLink of fers on fiber facilities, the rates, terms and conditions will be as set forth in the tariff or agreement under which CenturyLink offers the replacement service that the interconnecting entity selects. CenturyLink, separately from this notice, will provide interconnecting entities with further information regarding service migration options that CenturyLink offers.

Locations, Timing of Deployments & Interface Requirements:

The following gives additional details on the copper retirement(s):

STATE FL	WIRE CENTER Lehigh Acres LHACFLXA	PLANNED COMPLETION OR RETIREMENT DATE 8-30-2017	DA (s)	Job# N.088416	Replacing Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier
					system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
FL	Ft. Myers Beach FTMBFLXA	8-30-2017	1007 1008 2001 2007 6120B	N.095959 N.095972 N.095978 N.096002 N.051468	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
ОН	North Benton NBENOHXA	8-30-2017	R07	N.129961	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
VA	Charlottesville CHVLVAXA	8-30-2017	CM73 CM421	N.135075 N.108988	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
WI	Park Falls PKFLWIXA	8-30-2017	N/A N/A	N.065553 N.118215	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
WI	Wabeno WABNWIXB	8-30-2017	N/A N/A	N.122026 N.117963	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
WI	Laona LAONWIXD	8-30-2017	N/A N/A	N.127410 N.127411	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

Additional Information: Any person desiring additional information in conjunction with this Public Notice can contact:

Abdennaceur Boudhaouia Regulatory Compliance Director 303-707-8561

Jamal.Boudhaouia@CenturyLink.com